

Certificate

The Inspection Company **SBP outdoor / V.O.F. S.B.P.** has inspected:

Ropes Course:	Het Buitencentrum		
Location:	Hoogstraat 52 6611BZ Overasselt Nederland		
Parts Inspected:	Trapeze	constructed by	Active Construction Service b.v.
	Klimbos	constructed by	Active Construction Service b.v.
	Reuzenladder	constructed by	Active Construction Service b.v.

The inspection was carried out according to the ERCA guidelines for
Periodical Ropes Course Inspections

Please note and observe the results of the inspection, highlighted in the inspection report.
All action points must be fulfilled within the agreed timescale to validate this certificate.

Given that all remarks from the inspection report has been heeded carefully, as well as all action points
and repairs have been completed, then the ropes course shall be considered as ...
... Conform to EN 15567-1:2015 Part 7.1.4 Clause a-h

Date of Inspection: 03.02.2020
Certificate Number: 202000016

SBP outdoor / V.O.F. S.B.P. (Witrijtseweg 15, NL-5571 XJ Bergeijk, Nederlande):

Inspector Frank Schilders

This document was issued electronically and therefore contains no signature.