

Certificate

The Inspection Company **SBP outdoor / V.O.F. S.B.P.** has inspected:

Ropes Course: Het Buitencentrum
Location: Hoogstraat 52
Overasselt
Nederland
Parts Inspected: Klimbos, constructed by Active Construction Service
klimbomen en b.v.
reuzenladder

The inspection was carried out according to the ERCA guidelines for
Periodical Ropes Course Inspections

Please note and observe the results of the inspection, highlighted in the inspection report.
All action points must be fulfilled within the agreed timescale to validate this certificate.

Given that all remarks from the inspection report has been heeded carefully, as well as all action points
and repairs have been completed, then the ropes course shall be considered as ...

... Conform to EN 15567-1:2015 Part 7.1.4 Clause a-h

... Conform to ERCA Standards for Mobile and Permanent Ropes Courses

Date of Inspection: 03.02.2020
Certificate Number: 202000043

SBP outdoor / V.O.F. S.B.P. (Witrijtseweg 15, NL-5571 XJ Bergeijk, Nederlande):

Inspector Frank Schilders

This document was issued electronically and therefore contains no signature.